DATA SHEET



DiGMESA

EPI Arnite Part number: 930-0501/V01

 Image: 010-66700899

 Fax
 010-80688358

 E-mail:
 zxaf@zxaf.com

 http:
 www.zxaf.com

General Description

The EPI flowmeter is specifically suitable for fluid flow rate measurement of highly viscose media such as syrup, oil or detergent concentrates. Thanks to its special design and the epicycloid wheels, the EPI flowmeter is highly precise and allows extremely accurate flow measurement with minimal pressure loss.

Specific applications: Highly viscous media, high temperatures, high flow rates with low pressure loss and good chemical resistance.

Approvals / Standards

EN55014-1:00+A1:01+A2:02, EN61000-6-3:01+A11:04, IEC61000-6-3:06(ed.2.0), EN61000-3-2:06, IEC61000-3-2:05(ed.3.0), EN61000-3-3:95+A1:01+A2:05, IEC61000-3-3:94+A1:01+A2:05(Cons.ed 1.2), EN55014-2:97+A1:01, EN61000-6-1:01, IEC61000-6-1:05(ed.2) CE

	Technical data:		Electrical connection ratings:	
PBT 35% GF (Arnite)	Flow rate:	0.06 - 16.0 l/min	Power supply:	4.5—24 V DC
Inox 1.4435		depending on viscosity	Consumption:	5 mA to max. 13 mA
Aluminium oxide on request	Measuring accuracy:	+/- 1.0%	Signal connection:	Open collector NPN
FPM (Viton)		depending on viscosity	Signal voltage:	O V GND
EPDM on request	Repetition:	<+/- 0.25%	Signal load:	max. 20 mA
PEEK	Temperature range:	-10°C to $+65^{\circ}$ C	Leakage current:	max. 10 μΑ
NdFeB (Neodym)	D	14°F to 149°F	Connections:	3-pin AMP 2.8 x 0.8 mm
(not in contact with the medium)	Pressure range:	10 bar at 20°C 145 psi /68°F	Cianal	Square-wave output
	Mounting position:	Horizontal recommended	Duty Cycle:	$50\% / \pm 3\%$
	Nozzle size:	Ø 7.0 mm		
	Viscosity range:	approx. 5 - 8000		

centistokes

Material:

Housing: Bearing pin:

0-ring:

Turbine:

Magnets:







We reserve the right to make modifications in the interests of technical progress

RESISTANCE

Special regulations which must be complied with by the flowmeter manufacturer apply to each country, e.g. CE, NSF, FDA and SK. The various media flowing through the flowmeter differ from application to application. You are advised to enquire with the medium manufacturer as to whether the entire installation and the flowmeter are resistant to the medium itself (see Material)!

> ☎ 010-66700899Fax 010-80688358 E-mail: zxaf@zxaf.com http://www.zxaf.com

DIGMESA electronic circuitry is always designed for operation with DIGMESA flowmeters. Please note the following if connecting to other electronic circuitry:

• The flowmeter does not supply an output voltage but switches the signal terminal to 0 V ground (actuated) or leaves it open (nonactuated)

• There must be a pull-up resistor between power supply + and signal depending on electronic circuitry!

Version 01 EPI 930-0501/V01 GB Pone 2-5



Interface Connection: Examples Open Collector



We reserve the right to make modifications in the interests of technical progress

a 010-66700899 Fax 010-80688358 E-mail: zxaf@zxaf.com http: www.zxaf.com Version 01 EPI 930-0501/V01 GB Page 3-5

Measurement Curve EPI Ø7.00 mm





Medium for these linearity and pressure loss curves: Cola syrup (approx. 24 centistokes).

Nozzle size	Pulses/litre	g/pulse	min. flow rate in litres/min at Linear start	max. flow rate in litres/min	Pressure loss
Ø 7.00 mm	462	2.166	0.0653	5.35	0.29

The min. and max. flow rate and the pressure loss may vary depending on viscosity.

• N

The values specified must be considered as approximate values.

The number of pulses per litre may differ depending on medium and installation. We recommend to calibrate the number of pulses per litre in line with the complete installation.

MEASUREMENT TIPS

- Ensure that there is no fast-pulsatory movement of the media
- Ensure that there are no reverse pressure surges
- Ensure that there is no air in the system
- Note the mounting position of the flowmeter
- Min/max flow should be in the linear range of the selected flowmeter
- Clean the system at appropriate intervals
- Avoid electrical current peaks
- Incorrect cabling of power supply +, signal and ground will destroy the flowmeter
- Do not mechanically load electrical contacts
- Avoid moisture on the electrical contacts
- Avoid stray pick-up via the cable (Do not lay cables in parallel with high current loads)

We reserve the right to make modifications in the interests of technical progress .

Spare parts:



We reserve the right to make modifications in the interests of technical progress .

Version 01 EPI 930-0501/V01 GB Page 5-5

